







RECTANGEL DESK AND CHAIR


ASSEMBLY INSTRUCTIONS

TH-3012




PARTS AND FITTING PACKAGING DETAIL

A. Top	1 pc	B. Legs	4 pc	C. Support Leg	2 pc
					
D. Cross Bar	1 pc	E. Support Corner	2 pc	F. Seat Bench	2 pc
					


FULLY ASSEMBLED



HARDWARE* PACKED IN BOX #1

Allen Head Bolt \varnothing 8x40mm	Allen Head Bolt \varnothing 6x35mm
	
H1	H2
24 pc	12 pc
Allen Key 4x60mm	
	
H3	
1 pc	

YOUR BOX MAY CONTAIN EXTRA HARDWARE



This ruler is for hardware's measure


Be sure to check all packing material carefully for small parts, which may have come loose inside the carton during shipment.

RECTANGEL DESK AND CHAIR

TH-3012


ASSEMBLY INSTRUCTIONS

Step 1:



H1	8 pcs
----	-------

Step 2:




H1	8 pcs
----	-------

RECTANGEL DESK AND CHAIR

TH-3012


ASSEMBLY INSTRUCTIONS

Step 3:



H2	4 pcs
----	-------

Step 4:



H2	8 pcs
----	-------

RECTANGEL DESK AND CHAIR

TH-3012

ASSEMBLY INSTRUCTIONS

Step 5:

